

Page - 1

**Minutes of meeting
Grievance Meeting
ADP Scheme "Revamping of Emergency Services in Tertiary Care Hospitals in Punjab
(Sheikh Zayed Hospital, Rahim Yar Khan)"**

A meeting of grievance committee was held on 22-01-2020 at 10:00 a.m in the committee room of this institution under the chairmanship of Prof. Dr. Masood ul Haq, Prof. of Pulmonology SZMC, Rahim Yar Khan.

Agenda: To discuss & finalized the grievances submitted by the firms against the technical evaluation

Proceedings: The meeting starts with the Recitation of Holy Quran. Committee decided to discuss & make the decision one by one as per agenda.

M/s Sial Traders

Sr. No	Item Name	Model	Make	Status	Observations (If Rejected)	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Suction Light duty	H-40	HERSILL,Spain	Sub-Responsive	Due to Authorization	Submitted the sole Authorization	Sole Authorization letter provided	Responsive
2	Suction Heavy duty	H-40	HERSILL,Spain	Sub-Responsive	Due to Authorization	Submitted the sole Authorization	Sole Authorization letter provided	Responsive

M/s Medequips

Sr. No	Item Name	Model	Make	Status	Observations (If Rejected)	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Mobile X-Rays Unit	Cyber Mobil TS - 30 M	Primax Int., France	Sub-Responsive	Sole Authorization & OEM	Authorization & OEM Submitted by the firm	authorization submitted by the firm	Responsive
2	Echocardiography Machine	Aplio-300	Canon, japan	Non Responsive	Display modes not mentioned	Details provided in the bid	Display modes & twin view is available	Responsive

M/s Medequips Vs Bio-Tech Services

Sr. No	Item Name	Model	Make	Status	Observations Raised By Medequips	Reply by the firm	Review by the Technical Member	Decision of the Committee
9	Echocardiography Machine	MyLab X6	ESAOTE, Italy	Responsive	1-MyLab X6 does not have contrast Harmonic imaging provision. 2-MyLab X6 does not have provision of pediatric TEE Probe	1-Contrast Harmonic Imaging is available 2-Pediatric TEE probe is available	Observations are not valid	Responsive

(Handwritten signatures and initials are present at the bottom of the page, including a large signature on the left and several initials across the bottom.)

M/s Bio-Tech Services

Sr. No	Item Name	Model	Make	Status	Observations	Reply by the firm	Review by the Technical Member	Decision of the Committee
10E	Deibrillator	Cardio-Aid 360B	Innomed Medical, Hungary	Non-Responsive	1-Synchronized output with ECG 2-Charging time 3-Auto Test 4-Semi Automatic	1-Synchronized Output with ECG is available. 2-Charging time is 2.7/200j & 4.5S/360 J 3-Auto test function is available 4-AED Facility is available	Observations cleared with the help of technical literature	Responsive

M/s Bio-Tech Services Vs Radiant Medical

Sr. No	Item Name	Model	Make	Status	Observations Raised By Bio-Tech Services	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Defibrillator	M2	Zoll Medical USA	Responsive	1-Model is not available on the Website & don't have Color Display	M Series is available on the website	Observation is not valid	Responsive

M/s Bio-Tech Services Vs Sigma Int.

Sr. No	Item Name	Model	Make	Status	Observations Raised By Bio-Tech Services	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Defibrillator	Reanibex 700	Osatu, Spain	Non-Responsive	1-Color Display is not available only monochrome display system 2-EtCo2 module is not available 3- No Sale Ref.	1-LCD Display is 5.7" 2-ETCO2 change the model as Reanibex-800	ETCO2 is not available in Reanibex 700 No Sale Ref. provided	Non-Responsive

M/s Digionics Pvt. Ltd

Sr. No	Item Name	Model	Make	Status	Observations (If Rejected)	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Mobile X-Rays Unit	TMB 320	Technix, Italy	Sub-Responsive	Automatic over load protection	Submitted a copy of User Manual showing Automatic line Compensation	Observation cleared with the help of Tech. Brochure.	Responsive

M/s Varizon

Sr. No	Item Name	Model	Make	Status	Observations (If Rejected)	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Operating Laparoscope	Endocam Logic	Richard Wolf, Germany	Non-Responsive	1-Imaging system don't have backward & forward compatibility for upgradation 2-Picture in Picutre mode control via camera head botton is not mentioned. 3-Peripheral control is not available 4-5 individual preset & 3 patient data backup is not mentioned.	1-Future upgradation is avialalbed 2-Picture in picuture is avialable 3-Peripheral control is available 4-Individual preset and 3 patient data backup is available	Observations 2,3 & 4 got cleared with help of technical data leaflet & bid future upgradation for forward & back ward compatibility is not cleared	Responsive

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

M/s Biotech Pakistan Pvt. Ltd

Sr. No	Item Name	Model	Make	Status	Observations (If Rejected)	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Diathermy/ Electrosurgical Unit	Vio-3005	Erbe Elektromedizin, Germany	Sub-Responsive	Due to automatic self test function	Firm Submitted a copy of technical leaflet .	Self Test function is available (Literature is attached)	Responsive

M/s Hospital Supply Co.

Sr. No	Item Name	Model	Make	Status	Observations (If Rejected)	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	RO System	AMS-1500 GPD	HSC Assembled in Pak	Non Responsive	Imported (Country ??)	Basic component (USA) CE Certified	Observations cleared	Responsive
2	RO Plant	AMS-6000GPD	HSC Assembled in Pak	Non Responsive	Imported (Country ??)	Basic component (USA) & CE Certified	Observations cleared	Responsive

M/s Hospicare

Sr. No	Item Name	Model	Make	Status	Observations (If Rejected)	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	ECG Machine	ECG 200+	Cardioline, Italy	Non-Responsive	Thermal Recorder for printing 12 channels simultaneously	Submitted a copy of catalogue (highlighted)	Observations got cleared	Responsive

M/s Al-Kareem Medical

Sr. No	Item Name	Model	Make	Status	Observations (If Rejected)	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Baby Warmer	IW-400	Andromeda, USA	Non-Responsive	1-Manual Heat out pur control 2-Pivot Arm Technology for heating 3-Integrated Observation Lamp 4-Operating Modes selection	submitted the literature: -Manual Heat output -Horizontally heater can be adjusted -LED observation light is built in -Three modes selection is available	Observations cleared	Responsive

M/s Al-Kareem Medical Vs Vital Care

Sr. No	Item Name	Model	Make	Status	Observations Raised By AL-Kareem	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Cardiac Monitor	PM-2000XL-Pro	Advance Inst., USA	Responsive	1-No Past Performance, Experience & Satisfactory report	Past performance & supply order is available	Observations are not valid Supply order CMH & Past performance Jinnah Hospital	No reply from the firm (Principal Manufacturer). No Embassy attested authorization submitted

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

M/s Bio-Tech Services Vs SIEMENS Pakistan

Sr. No	Item Name	Model	Make	Status	Observations Raised By Bio-Tech Services	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Color Doppler	Acuson NX3	SIEMENS, Germany/ USA/ China	Sub-Responsive	1-NX3 does not have upgradability for 4D imaging 2-Quoted Model only support the frequency range 1.3 - 12 MHz that shows that linerr proble 7-14 MHz cannot be operated. 3-NX3 does not have facility for Needle Navigation with tracking system	1-NX3 is upgradable to 3D & 4D imaging, data sheet attached 2-NX3 support upto 1-20 MHz literature attached 3-NX3 have the Needle navigation with tracking System	Observations of Bio-Tech Services are not valid	Responsive

M/s SIEMENS Pakistan

Sr. No	Item Name	Model	Make	Status	Observations (If Rejected)	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Color Doppler	Acuson NX3	SIEMENS, Germany/ USA/ China	Sub-Responsive	1-Don't have Doppler Beam Streaming 2- 200 db system dynamic range or more.	1-The system have beam Steaming are available 2-Dynamic range is 227db	Observations cleared	Responsive

M/s Almed Solutions

Sr. No	Item Name	Model	Make	Status	Observations (If Rejected)	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Operating Laparoscope	Multi	Karl Storz SE & Co Kg	Non-Responsive	1-Imaging system don't have backward & forward compatibility for upgradation 2-Image enhancement mode is not available 3-Control of peripheral via camera head botton is not mentioned 4-RGB signal to D-Sub Socket not mentioned 5-SDI signal to DVI Socket with DVI module 6-HDTV Signal to DVI D-Socket	Firm submitted the reply: 1-The system is compatible for both forward & Backward upgradation with three chip CCD Camera Heads, Single chip COMS Full HD camera heads and can be upgraded to use 4K Heads & future Technology. 2-The System have 5 Image enhancement modes (Clara, Chroma, Clara+Chroma, and SPectra A & B) 3-The System is able to control light source and endoflator via Camera Head Botton via SCB Cables. 4-RGB TO D Sub Socket, SDI to Signal to DVI Socket & HDTV Signals to DVI D-Socket can be used for HDTV Signals	Observations cleared from the technical leaflet	Responsive

[Handwritten signatures and marks at the bottom of the page]

M/s Bestech Ent.

Sr. No	Item Name	Model	Make	Status	Observations Raised By AL-Kareem	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Medical Gasses	Multi	G.Samara, Greece	Non-Responsive	Compressor type is vertical	Firm Submitted the reply claiming that their offered Compressor is as per specifications	Observation is not cleared. Demanded compressor is reciprocating type while offered is screw type	Non-Responsive

M/s Endo Kare (Part-A) and

M/s Mediland Pakistan Vs Endo Kare (Part-B)

Sr. No	Item Name	Model	Make	Status	Observations by Committee	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	HD Video Gastroscope (A)	Multi	Olympus, Japan Sinapur	Sub-Responsive	<p>(Part-A) Quoted Model is HD Video Gastroscope Therapeutic instead of HD Video Gastroscope</p> <p>Not offered</p> <p>Auto Disinfector State of Art Storage Cabinet Drying cabinet with full traceability for equipment safe storage Storage upto 5-10 Endoscopes for 30 days storage</p> <p>HEPA Filtered air supplied to each endoscope ensure dry channels</p> <p>water jet function is not available or mentioned</p> <p>(Part-B) the monitor quoted by M/s Endo Kare is from China</p>	Documents provided by the firm	<p>(Part-A) Observations of water jet function are not replied by Endo Kare</p> <p>Mediland made observation of incomplete offer also</p> <p>(Part-B) As per bidding document (Health & SZMC) 3: Country of origin "3.1: Country of Manufacturer should be from USA, Europe & Japan, unless otherwise any other country of manufacturer is mentioned in the specifications. However, country of origin of equipment could be from any geographical region of the world as per law of Pakistan"</p>	<p>Responsive (Part A&B) (The End User made the opinion that SZMC/SZH required Therapeutic Gastroscope as per PC-I)</p> <p>For Financial comparison cost of accessories will not be included in the cost of M/s Endo Kare while</p> <p>M/s Meiland will provide water jet function</p>
	HD Video Gastroscope (B)	Multi	Olympus, Japan Sinapur					
	HD Video Colonoscope (C)	Multi	Olympus, Japan, UK Sinapur					
	Duodeno Video Scope (D)	Multi	Olympus, Japan, UK Sinapur					
	HD Video System Centre (E)	CV-190	Olympus, Japan, UK Sinapur					
	Xenon Light Source 300 W (F)	CLV-190	Olympus, Japan, UK Germany					
	Work station for Endoscope room (G)	TC-C4	Olympus, Japan, UK Germany					
	Medical Grade Monitor (H)	LMD 2735	Olympus, Japan, UK Germany					

[Handwritten signature]

[Handwritten signatures]

[Handwritten signature]

M/s Endo Kare Vs Mediland Pakistan

Sr. No	Item Name	Model	Make	Status	Observations Raised By Mediland	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	HD Video Gastroscope (A)	EG-27i10	Pantex, Japan	Responsive	18-A & B Water Jet Function is not offered. The latest amended PVMS has included this functions	In Video Gastroscope Water Jet function not demanded in the specifications	In Video Gastroscope Water Jet function not demanded in the specifications	<p>Responsive</p> <p>(The End User made the opinion that SZMC/SZH required Therapeutic Gastroscope as per PC-I)</p> <p>For Financial comparison cost of accessories will not be included in the cost of M/s Endo Kare while</p> <p>M/s Meiland will provide water jet function</p>
	HD Video Gastroscope (B)	EG-27i10	Pantex, Japan					
	HD Video Colonoscope (C)	EC 34i10L	Pantex, Japan					
	Duodeno Video Scope (D)	ED 34 i10T	Pantex, Japan					
	HD Video System Centre (E)	EPK i7010 Optivista	Pantex, Japan					
	Xenon Light Source 300 W (F)	Integrated Optivista	Pantex, Japan					
	Work station for Endoscope room (G)	Endo 350	Pantex, Japan					
	Medical Grade Monitor (H)	NDS Surgical Imaging	Radiance, USA					

M/s Endo Kare Vs Clinical Life

Sr. No	Item Name	Model	Make	Status	Observations Raised by Endo Kare	Reply by the firm	Review by the Technical Member	Decision of the Committee
	Operating Laparoscope	CMOS 1/2" Chip	Ackermann, Germany	Non-Responsive	<p>1-No Forward Compatibility and Modularity</p> <p>2-Picture in picture mode control via camera head button is not available</p> <p>3-Control of peripheral devices through Camera Head button isn't available.</p> <p>4-Video Capturing in Full HD is not available</p> <p>5-No Video Recorder with 500 GB hard disk</p> <p>6-No Sale Reference & Past performance</p> <p>7-Latest image enhancement mode is not available</p>	<p>1-Imaging System backward & forward compatibility available for upgradation (Data sheet attached)</p> <p>2-Both options Picture-in-picture & Picture out mode available. User can control via camera head buttons or via HD Monitor</p> <p>3-Two peripheral outputs & control with camera head button available.</p> <p>4-Integrated HD Quality video recording of MPEG4 format available with camera head buttons</p> <p>5-06 Individual preset available.</p> <p>6-Unlimited user profile & Up-to nine patient data-backup available.</p> <p>7-Sale Reference & Past performance Certificate attached.</p>	<p>1-Backward & Forward compatibility is available</p> <p>2-Picture in Picture mode is available in Camera & Monitor</p> <p>3-Peripheral control is available</p> <p>4-Integrated HD Camera recording is possible in MPEG4 format</p> <p>5-Six preset available</p> <p>6-Unlimited User profile data is possible for 9 patients</p> <p>7- Sale Reference & Past performance attached</p>	Responsive

[Handwritten signature]

[Handwritten signatures]

[Handwritten signature]

M/s Endo Kare Vs Almed Solutions

Sr. No	Item Name	Model	Make	Status	Observations Raised By Endo Kare	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Operating Laparoscope	Multi	Karl Storz SE & Co Kg	Non-Responsive	1-Video Capturing in full HD is not available 2-No Video Recorder with 500 GB Hard Disk Local hose Pipe offered instead of original	1-Video Capturing in full HD is available 2-Integrated Built in recording facility which can be stored through USB on mass storage device western digital 500GB 3-HP Hose pipe will be provided from same manufacturer	USB Mass storage device instead of 500 GB Hard Disk Other observations got cleared	Responsive

M/s Endo Kare Vs Verizon

Sr. No	Item Name	Model	Make	Status	Observations Raised By Endo Kare	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Operating Laparoscope	Multi	Karl Storz SE & Co Kg	Non-Responsive	1-Latest image enhancement mode not available 2-No forward compatibility and modularity 3-Picture in picture mode cannot be controlled via camera head button 4- No video recorder with 500 GB hard disk	1-Image enhancement mode (SIM) is available. 2-Forward compatibility and modularity is available 3- Picture in picture mode can be controlled with camera head button. 4-Camera system has built in USB with 1 TB hard drive for imaging & video	Observations raised by Endo Kare are rejected	Responsive

M/s Endo Kare Vs Noor Int.

Sr. No	Item Name	Model	Make	Status	Observations Raised By Endo Kare	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Operating Laparoscope	Multi	STEMA	Non Responsive	1-No Sale Ref. in Teaching Hospital 2-Latest Image enhancement mode is not available 3-No forward compatibility & Modularity 4-automatic white balance not available 5-Control of peripheral devices through Camera Head button isn't available. 6-Video Capturing in Full HD is not available 7-Insufflator is not as per specifications 8-No Video Recorder with 500 GB hard disk	1-Sale Ref. is provided with the technical offer 2-Image enhancement mode is available 3-Forward Compatibility and Modularity is available 4-Automatic white balance is available. 5-Control of peripheral devices through camera head button is available through MIS Bus interface. 6-Video Capturing is available in full HD Mode 7-INSufflator required in tender is 40-50 Liters while our quoted is 45 liters. 8-Offered MEDICAPTURE Medicap USB 300 HD Internal storage. 320 GB additional with 2 high speed connector	Offered MEDICAPTURE Medicap USB 300 HD Internal storage. 320 GB additional with 2 high speed connector (500 GB Hard drive as per specifications) Observations by Endo Kare are rejected	No sale Reference was provided, Hence Non-Responsive

[Handwritten signature]

[Handwritten signatures]

[Handwritten signature]

M/s Medlinad Pakistan Vs Total Technologies

Sr. No	Item Name	Model	Make	Status	Observations Raised By Mediland	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Electronic Autoclave 1STU	UNISTERI SL 336 1	MMM Group, Cz. Republic	Responsive	1-The quoted model by M/s Total Technologies doesn't have Integrated Printer which is a major deviation 2-Manual Door instead of automatic door	1-External printer can also be attached 2-Doors are automatic	Don't have integrated printer DOORS are automatic	Responsive (New Brochure shows availability of Built in Printer)

M/s Medlinad Pakistan Vs Radiant Medical

Sr. No	Item Name	Model	Make	Status	Observations Raised By Mediland	Reply by the firm	Review by the Tech. Member	Decision of the Committee
1	Electronic Autoclave 1STU	S101E-1	Matachana, Spain	Responsive	1-The quoted model by M/s Radiant Medical is not available on official website, And Quoted model does not have any brochure. 2-Manual Door instead of automatic door	1-Available on the website as S100 series. Brochure is attached with technical offer 2- Doors are automatic as in the technical leaflet of bid	Observations are not correct doors are automatic	Responsive

M/s Medlinad Pakistan Vs Clinical Life

Sr. No	Item Name	Model	Make	Status	Observations Raised By Mediland	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Electronic Autoclave 1STU	Steri 21 AJC 404066-ID GI	A.J. Costa, Portugal	Non-Responsive	Material Standard are not as per PVMS specifications Standard. Chamber, Jacket and doors are not made of AISI 316L. 2-Safety Interlocks are absent	1-Material standard is AISI 316L 2-Safety lock are available	observations are not valid	Responsive
2	Medium Steam Sterilizer 4STU	Amaro 5000-707070 - 2D GI	A.J. Costa, Portugal	Non-Responsive	Material Standard are not as per PVMS specifications Standard. Chamber, Jacket and doors are not made of AISI 316L. 2-Safety Interlocks are absent	1-Material standard is AISI 316L 2-Safety lock are available	observations are not valid	Responsive
3	Electronic Autoclave 1STU Medium Steam Sterilizer 4STU	Amaro 5000-707070 - 2D GI	A.J. Costa, Portugal	Non-Responsive	Both Models are vertical autoclave are laboratory purpose as mentioned on the Technical leaflet	Company offer both types of products. These offered Models are for Hospital Use	observations are not valid	Responsive

M/s Eastern Medical

Sr. No	Item Name	Model	Make	Status	Observations (If Rejected)	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Medical Gasses	Multi	Multi	Non-Responsive	The Compressor is not reciprocating type	As per PVMS Specifications Screw type Compressor is acceptable	Non -Responsive	Non -Responsive

M/s Eastern Medical Vs Hospicare

Sr. No	Item Name	Model	Make	Status	Observations Raised By Eastern Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	ICU Ventilator	Puritan Bennett PB 840	Medtronic Covidien AG USA	Responsive	1-Screen size is not correct 2-Qouted Model is an old Technology 3-No Built in Nebulizer	See the Technical Offer	Screen size not verified & Nebulizer is not built in/ Integrated	Non-Responsive

M/s Eastern Medical Vs Human Healthcare

Sr. No	Item Name	Model	Make	Status	Observations Raised By Eastern Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Electrohydraulic OT Table	OUK-02 (Beta)	Medin, Belarus	Responsive	1-There is no sale Reference/ Past Performance	Sale Ref. is attached (Mayo Hospital LHR)	Verified from the Bid Observation Rejected	Responsive
2	CTG Machine	FM-10	Mediblu, USA	Responsive	1-FDA Certificate 2-No Sale Reference	Sale Ref. is attached (DHQ, Gujrat, BBH Rwp)	Verified from the Bid Observation Rejected	Non-Responsive

M/s Eastern Medical Vs Medequips

Sr. No	Item Name	Model	Make	Status	Observations Raised By Eastern Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Electrohydraulic OT Table	KM-402	Paramount, Japan	Responsive	Lateral Tilt adjustment is 20 Degree	Tilt degree is 25 degree	Verified from the technical leaflet Observation rejected	Responsive

M/s Eastern Medical Vs Total Technologies

Sr. No	Item Name	Model	Make	Status	Observations Raised By Eastern Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Electrohydraulic OT Table	Lojer Scandia SC 440	Lojer Oy, Finland	Responsive	1-Back section adjustment is -10deg, to +70 deg	Back Section Adjustment is - 10 degree	Verified from the bid Observation Accepted	Non Responsive
2	Operation Theatre Light	Emaled-560	Emaled, Germany	Responsive	1-Sale Ref. is not available	-	No Sale Reference/Supply Order is attached.	Responsive

M/s Eastern Medical Vs Sial Traders

Sr. No	Item Name	Model	Make	Status	Observations Raised By Eastern Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Electrohydraulic OT Table	T-3600	ORICARE, USA	Responsive	1-FDA Certificate 2-No Sale Reference	-	No Sale Ref. provided Observation Accepted	Responsive

M/s Eastern Medical Vs AL-Kareem

Sr. No	Item Name	Model	Make	Status	Observations Raised By Eastern Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	CTG Machine	FM-3000	Advance Inst. USA	Responsive	1-FDA Certificate (510K) 2- Agency Agreement	-	Agency Agreement verified from the bid, & FDA (510) K not verified	Responsive

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

M/s Medlink Traders

Sr. No	Item Name	Model	Make	Status	Observations Raised	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Cardiac Monitor	Oxy-PM2000E	Oxytech, UK	Non-Responsive	NO CDR/ BG was attached	Copy attached	No CDR/ BG attached	Non- Responsive
2	ECG Machine	OXY ECG1200B	Oxytech, UK	Non-Responsive	NO CDR/ BG was attached		No CDR/ BG attached	Non- Responsive
3	Trolley for Patient Shifting	Camel	Formed Pro, Poland	Non-Responsive	NO CDR/ BG was attached		No CDR/ BG attached	Non- Responsive
4	Neonatal Monitor	OXY-PM2000E	Oxytech, UK	Non-Responsive	NO CDR/ BG was attached		No CDR/ BG attached	Non- Responsive
5	CTG Machine	OXY-FM10F	Oxytech, UK	Non-Responsive	NO CDR/ BG was attached		No CDR/ BG attached	Non- Responsive
6	Sonic Aid/ Fatal Heart Detector	OXY-FM10F	Oxytech, UK	Non-Responsive	NO CDR/ BG was attached		No CDR/ BG attached	Non- Responsive

M/s Umar Traders

Sr. No	Item Name	Model	Make	Status	Observations Raised By	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Hand Sanitizer	Local	Local, Pakistan	Non-Responsive	NO CDR/ BG was attached	Copy attached	No CDR/ BG attached	Non- Responsive
2	Fowler Bed with Mattresses	Local	Local, Pakistan	Non-Responsive	NO CDR/ BG was attached		No CDR/ BG attached	Non- Responsive
3	Instrument Trolley	Local	Local, Pakistan	Non-Responsive	NO CDR/ BG was attached		No CDR/ BG attached	Non- Responsive
4	IV Stand	Local	Local, Pakistan	Non-Responsive	NO CDR/ BG was attached		No CDR/ BG attached	Non- Responsive
5	Air Conditioner	-	Pel, Pakistan	Non-Responsive	NO CDR/ BG was attached		No CDR/ BG attached	Non- Responsive
6	Examination Caouch	Local	Local, Pakistan	Non-Responsive	NO CDR/ BG was attached		No CDR/ BG attached	Non- Responsive
7	Fowler Bed with Mattresses	Local	Local, Pakistan	Non-Responsive	NO CDR/ BG was attached		No CDR/ BG attached	Non- Responsive
8	Medicine Trolley	Local	Local, Pakistan	Non-Responsive	NO CDR/ BG was attached		No CDR/ BG attached	Non- Responsive
9	Outlet Forceps	Local	Local, Pakistan	Non-Responsive	NO CDR/ BG was attached		No CDR/ BG attached	

M/s Vital Care

Sr. No	Item Name	Model	Make	Status	Observations Raised	Reply by the firm	Review by the Tech. Member	Decision of the Committee
1	Suction Machine (Lt Duty)	Eurovac-H40	HERSILL, Spain	Sub-Responsive	Authorization & OEM	Authorization & OEM Provided	Verified	Subject to email. The Principal Manufacturer in its email. asked to discard M/s Vital Care's authorization, Hence Non-Responsive
2	Suction Machine (H. Duty)	Eurovac-H40	HERSILL, Spain	Sub-Responsive	Authorization & OEM	Authorization & OEM Provided	Verified	

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

M/s Vital Care Vs Al-Kareem

Sr. No	Item Name	Model	Make	Status	Observations Raised By Vital Care	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Diathermy/ Electro-surgical Unit	ESU-400	Advance Instruments, USA	Responsive	1-FDA with 510 K Certificate	-	Not Verified	Non- Responsive

M/s Vital Care Vs Human Healthcare

Sr. No	Item Name	Model	Make	Status	Observations Raised By Vital Care	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Cardiac Monitor	DS7000	Digital Science Technology	Responsive	1-FDA with 510 K Certificate	-	FDA with 510K not verified	Non- Responsive

M/s Vital Care Vs Sial Traders

Sr. No	Item Name	Model	Make	Status	Observations Raised By Vital Care	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Cardiac Monitor	M-7610	Oricare, USA	Responsive	1-FDA with 510 K Certificate	-	FDA without 510 K verified Also have CE Certificate	Non-Responsive

M/s Vital Care Vs Med Impex

Sr. No	Item Name	Model	Make	Status	Observations Raised By Vital Care	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Cardiac Monitor	Data Lysys 808	Lutech Ind. USA	Responsive	1-FDA with 510 K Certificate	-	FDA without 510 K verified	Non- Responsive

M/s Biologic Medical

Sr. No	Item Name	Model	Make	Status	Observations	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	CTG Machine	Team-3	Huntleigh Healthcare, UK	Non-Responsive	1.FHR range not mentioned. 2-Ultrasound transducer with marker & Alarm 3-Paper record speed	1-30-240 bpm Tech. leaflet 2-Fetal Movement event marker is a part of CTG 3-audible & visual notifications user adjustable 4-1,2,3 Cm/ Min/user selectable upto 15cm/ min	Observations cleared with the help of Technical leaflet attached with letter.	Responsive

M/s KSBN Int.

Sr. No	Item Name	Model	Make	Status	Observations	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Electronic Autoclave 1STU	AS 446	SMS, Poland	Non-Responsive	1-Past performance 2-Working Pressure Not mentioned 3-No Heat Exchanger/ Air Detector 4-Servo Motor stabilizer Not offered	1-Sale Ref. copy enclosed 2-Quoted Model has working pressure 32psi 3-Offered Model have Heat Exchanger 4-We will supply Stabilizer	1-No Past performance available 2- No sale Ref. Model is different in supply order 3-No Heat Exchanger & Water stabilizer facility find in the technical literature of Bid.	Non- Responsive

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

2	Medium Steam Sterilizer 4STU	AS 666	SMS, Poland	Non-Responsive	Built in water saving system, automatic heat exchanger & air detector	Our offered Model is time cycled, working pressure of 32 psi and have built in water saving system	1-Efficient Water system with Vacuum Pump 2-Heat Exchanger is available 3-Automatic air detector is not available	Responsive
---	------------------------------	--------	-------------	----------------	---	--	---	------------

M/s Noor Int.

Sr. No	Item Name	Model	Make	Status	Observations	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	ICU Ventilator	Hamilton G5	Hamilton Medical	Non Responsive	1-Tidal Volume 2-Respiratory Frequency	Inspiratory Tidal volume is 5ml to 2000 ml on Neonatal Mode Respiratory Frequency is 1-120 bpm	1-Tidal Volume & Respiratory Frequency got verified from Manual copy 2-Demo was not provided by Noor	Non-Responsive
2	Anesthesia Work Station	Caelus Lite	Medec, Belgium	Non Responsive	No Sale Ref. & Past Performance	Past Performance & Sale Ref. are enclosed with this letter	Sale Ref. provided	Non-Responsive

M/s Clinical Life Vs Noor Int.

Sr. No	Item Name	Model	Make	Status	Observations	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Anesthesia Work Station	Caelus Lite	Medec, Belgium	Non Responsive	1-O2, N2O & Air gauges are not available. 2-Pin Index yokes are not available 3-Integrated heated breathing system are not available 4-Digital flow meter are not available 5-Hypoxic device in the quoted model is not verifiable in the brochure 6-Quoted model of Monitor is not available on the website	-	1-observations (1,2,3 & 5) raised by Clinical Life stands technical leaflet. Only observation 4 is not valid Demo not provided	Non-Responsive

M/s G. Med Pvt. Ltd

Sr. No	Item Name	Model	Make	Status	Observations	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Diathermy/ Electrosurgical Unit	Excell 350 MCDSe	ALSA, Italy	Sub-Responsive		Due to Authorization Sole Authorization Certificate is attached	Authorization is not embassy attested	Responsive
2	Electrohydraulic/ Mechanical OT Table	Hiro	Formed, Poland	Non-Responsive	Optional items not quoted	Item No. 29 of Labor Room was without accessories that merged with Emergency OT Table. Therefore, we are offering accessories with this reply for consideration & opening with F. offer opening	Observation removed as optional item were not demanded for labour room (accepted)	Responsive
3	Ceiling OT Light	IGNIS 160C	Famed Lodz SA, Poland	Responsive	OEM Certificate Required	OEM is enclosed with this letter	OEM provided Observation removed	Responsive
4	CTG Machine	PG 800G	Progetti, Italy	Non-Responsive	Authorization Certificate Required	Authorization is enclosed with this letter	Authorization is not embassy attested	Responsive

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

5	Desktop Fetal Heart Detector/ Sonic Aid	Fetatrack DD250 Desktop doppler	Ultrasound Tech, UK/ Germany	Non-Responsive	Authorization Certificate Required	Authorization is enclosed with this letter	Authorization provided Observation Removed	Responsive
---	--	---------------------------------	---------------------------------	----------------	------------------------------------	--	---	------------

M/s Radiant Medical

Sr. No	Item Name	Model	Make	Status	Observations	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Baby Warmer	AMENIC E Servo	Ardo Medical, Switzerland	Non-Responsive	After Sale Certificate not attached	Copy of Certificate ensoed with this letter	Certificate provided Observation Removed	Responsive
2	Life Life Trolley	USRLU	Waterloo, USA	Non-Responsive	1-Walls in orange moulded strong Polymer 2-Color handles & Lable are not mentioned 3-Writing Surface and IV hooks are not risen coated steel 4-Shelve for Vaccume pump is not available	Offered Model is as per specifications	1-steel made with moulded polymer 2-Top surface for writing 3-Shelve for Vacuum Pump is available 4-Shelve for defibrillator is available Observations removed	Responsive
3	Medium Steam Sterilizer 4STU	S1004E-2	Matuchana, Spain	Non-Responsive	1-Built in Water Saving System is not available 2-Automatic heat Exchanger is not available 3-Air Detector is absent	1-Built in Water saving System is available 2-Automatic Heat Exchanger is available 3-Air Detector is available	1-water saving system is through water recirculation system (Observation removed) 2- Heat exchanger is available 3-Air detector is available	Responsive
4	R.O Plant	Local	Local	Non-Responsive	Manufacturing country is not mentioned	Pars imported form USA, Denmark & France	Observation removed	Responsive
5	Medical Gasses	Multi	Multi	Non-Responsive	1-Compressor is lubricant type (Not medical grade)	-Screw Type (latest) -Medical grade compressor need not to be oil free.	Compressor is not medical grade & Screw type	Non- Responsive

M/s Radiant Medical Vs Al-Kareem Medical

Sr. No	Item Name	Model	Make	Status	Observations Raised by Radiant Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Baby Warmer	IW-400	Andromeda, USA	Non-Responsive	1-The original Manufacturer is Zhengzhou Dislon Inst. China. 2-They don't have manufacturing Facility 3-Bed surface area is 670x540	Copy of Certificate ensoed with this letter	Quoted product verified from the Andromeda website, therefore, Observation rejected	Responsive

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

M/s Radiant Medical Vs KASBN Int.

Sr. No	Item Name	Model	Make	Status	Observations Raised by Radiant Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Baby Warmer	LN-91 G	Alfamedic, Cz, Republic	Responsive	The offered model does not have X-Rays Gring on side panel for X-Rays Cassette	Copy of Certificate enclosed with this letter	X-Ray grid facility is available verified http://www.alfamedic.cz/index.php/en/vyroby-en/neonatalogie-a-pediatric-en/65-inkubatory-en/58-vyhrivane-luzko-ln-91g-en	Responsive

M/s Radiant Medical Vs Bio-Tech Services

Sr. No	Item Name	Model	Make	Status	Observations Raised by Radiant Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Defibrillator	Cardio Aid 360B	Innomed Hungary	Non-Responsive	1-ETCO2 option is not available in the Model 2- Offered Model do not have 510 comply FDA 3-Charging time is <7 in battery operation 4-Innomed is eligible for free sale in European Market 5-Declared Non-Responsive in DHA T.T Singh	1-ETCO2 is available on technical leaflet of bid at page 1,6 2-as per tender USA, EU, Japan is the country of origin & we have EU origin with CE certificate 3-Charging time is 2.7 sec for 200 J & 4.5 Sec for 360 J 4-Innomed is eligible for free sale in EU Market.	1-CE Certificate is available but No FDA 2-Other Observations are not valid	Responsive

M/s Radiant Medical Vs Sigma Int.

Sr. No	Item Name	Model	Make	Status	Observations Raised by Radiant Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Defibrillator	Reanibex-700	Osatu, Spain	Non-Responsive	1-LCD Display is non-color is only monochrome 2-EtCO2 is not available	1-LCD Display is 5.7" 2-ETCO2 change the model as Reanibex-800	ETCO2 is not available in Reanibex 700	Non- Responsive

M/s Radiant Medical Vs Sial Traders

Sr. No	Item Name	Model	Make	Status	Observations Raised by Radiant Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Vaccume Extractor	H-40	Hersill Spain	Responsive	M/s Vital Care quoted same brand.	Authorization received through email	Authorization received through email	Responsive. Email received from Hersill, Sial has sole authorization, Hence Responsive

M/s Radiant Medical Vs Vital Care

Sr. No	Item Name	Model	Make	Status	Observations Raised by Radiant Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Vaccume Extractor	H-40	Hersill Spain	Responsive	M/s Sial Traders quoted same brand.		Authorization received through email	The Principal Manufacturer in its email. asked to discard M/s Vital Care's authorization, Hence Non-Responsive

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

M/s Radiant Medical Vs Sigma Int.

Sr. No	Item Name	Model	Make	Status	Observations Raised by Radiant Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Vacuum Extractor	Hospivac 400	CAMI, Italy	Responsive	Noise level is 46.5 db instead of 45 db	Noise Level is 46.4 db	Noise level is 46.4 against the requirement of 45db	Non-Responsive

M/s Radiant Medical Vs KASBN Int.

Sr. No	Item Name	Model	Make	Status	Observations Raised by Radiant Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	ECG Machine	Euro ECG 12 View	Lumed, Italy	Responsive	Lumed is not original Manufacturer which is Shenzen ECG MAC-China	Lumed Italy is the original manufacturer	Lumed is original Manufacturer. Model is available on its website https://www.lumed.com/en/product/hi-resolution-electocardiography	Responsive

M/s Radiant Medical Vs Medequips

Sr. No	Item Name	Model	Make	Status	Observations Raised by Radiant Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Mobile X-Rays	Primax Cyber	TS-30M	Sub-Responsive	Primax Int. France is not OEM rather Distributor	OEM Certificate provided with the reply of grievance letter.	Observation is not valid, hence rejected	Responsive

M/s Radiant Medical Vs Digionics

Sr. No	Item Name	Model	Make	Status	Observations Raised by Radiant Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Mobile X-Rays	TBM-320	Technix, Italy	Sub-Responsive	Poor after sale service of digionics	-	Past performance is not a monitoring parameter standard evaluation	No email or letter received from Services Hospital, Lahore

M/s Ashraf Nadeem

Sr. No	Item Name	Model	Make	Status	Observations Raised by Radiant Medical	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	RO System	Locally Assembled	Pacific Engr Lahore	Non-Responsive	No Sale Ref. & Past Performance	Sale Ref. & Past performance is enclosed with this letter	Observation settled/ Cleared	Responsive
2	RO Plant	Locally Assembled	Pacific Engr Lahore	Non-Responsive	No Sale Ref. & Past Performance	Sale Ref. & Past performance is enclosed with this letter	Observation settled/ Cleared	Responsive

M/s Total Technologies Vs Mediland

Sr. No	Item Name	Model	Make	Status	Observations Raised by Total Technologies	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Electronic Autoclave 1STU	HS 33	Getinge, Sweden	Responsive	1-Chamber, Jacket & doors made of AISI 304L/Ti 2-Verify CE certificate for Country of origin 3-Mediland is not the sole distributor of Pakistan 4-UPS should be offered by the manufacturer	1&2-The Sterilizer Chamber & jacket is constructed from solid high quality type 316LTi/W.Nr 1.4571 stainless steel for optimal protection against Corrosion. 3-Trans is a wholly owned factory by Getinge, Manufacturing is done at Trans by Getinge Medikal Aletler Sanayi Ve Tic A.S as per quality standards of Getinge. OEM is attached4-UPS will be supplied by Manufacturer	-Chamber & Jacket are not made of 316L. -The offered models are from Trans Medikal, Turkey while Mediland its country of origin, Sweden. Further, your representative failed to prove that Trans Medikal is a factory of Getinge in turkey. -Trans Medikal is not available on the website of Getinge, hence it was concluded that Trans Medikal is not the company/ factory of Getinge. -The offered model should be available on OEM website, which is available on http://transmedikal.com/urun/smart-s_330 while Getinge's original website http://www.getinge.com/int/products/hospital/sterlization doesn't declares this model on their website. It means Getinge is not the original manufacturer, rather trans Medikal is the OEM. Observations are valid	Non-Responsive
2	Medium Steam Sterilizer 4STU	TS330EC2 NX	Getinge, Sweden	Responsive	1-Offered Model is from Turkey Trans Medikal. Please check OEM 2-The offered Model don't have automatic heat exchanger 3-Mediland is not the sole distributor of Pakistan 4-UPS should be offered by the manufacturer	1--As per bidding document (Health & SZMC) 3: Country of origin "3.1: Country of Manufacturer should be from USA, Europe & Japan, unless otherwise any other country of manufacturer is mentioned in the specifications. However, country of origin of equipment could be from any geographical region of the world as per law of Pakistan" Country of manufacturer is Sweden 3-UPS will be provided from same Manufacturer	Observations of M/s Total Technologies were found correct in the meeting. M/s Mediland failed to prove that trans Medikal is the factory in Turkey owned by Getinge. Trans Medikal is not available on the website of Getinge. It shows Getinge is not OEM. Observations were valid	Non-Responsive

M/s Total Technologies Vs Clinical Life

Sr. No	Item Name	Model	Make	Status	Observations Raised by Total Technologies	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Ultrasonic Cleaner	QC6-02 Quick Clean	Newmed, Italy	Non-Responsive	Offered Model is a table top Unit not an integrated type	The offered model is integrated type (Recessed)	Integrated model is offered	Responsive

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

[Handwritten signature]

M/s Total Technologies Vs Radiant Medical

Sr. No	Item Name	Model	Make	Status	Observations Raised by Total Technologies	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Ultrasonic Cleaner	DT 1028 H 28	Bandelin for Matachana, Spain	Responsive	1-Offered Model is a table top Unit not an integrated type	-	Bedline is a manufacturer for Matachana, Spain. Model is integrated but don't have drain pipe	Responsive
2	Electronic Autoclave 1STU	S101E-1	Matachana, Spain	Responsive	Offered Model don't have digital display	-	Have a digital display	Responsive

M/s Total Technologies Vs Sigma Int.

Sr. No	Item Name	Model	Make	Status	Observations Raised by Total Technologies	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Ultrasonic Cleaner	Ultrasons HD 3000868	JP Selecta, Spain	Non-Responsive	1-Offered Model is a table top Unit not an integrated. 2-Model Not available on Website & manufacturer is another company	-	1-Offered Model is not integrated 2-offered model is on Ultrasons Observations are valid	Non-Responsive
2	Electronic Autoclave 1STU	P-3270 H	CISA, Italy	Non-Responsive	1-Don't have Sole Authorization certificate & Past experience	1-Sigma have Sole Authorization (p-54) 2-EDO Health Rawalpindi Ref. attached with grievance letter 184	Observations are not valid	Non-Responsive

M/s Umar Associates

Sr. No	Item Name	Model	Make	Status	Observations	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Water Cooler	DWC-65	Canon, Pakistan	Non-Responsive	Bid Validity not mentioned	Firm cleared that their bid is valid for 120 Days	Observation Removed	Responsive
2	Dust Bin	-	-	Responsive	Sample Required	Sample has been submitted	Observation Removed	Responsive
3	IV Stand	-	-	Responsive	Sample Required	Sample has been submitted	Can be accepted subject to sample approval	Sample not submitted, Non-Responsive
4	RO System	AMS-1000GPD	UA/ USA/ China/Taiwan	Non-Responsive	No Technical Data provided	Technical data provided with grievance letter	Data provided, Observation removed	Responsive
5	Air Condition	Orient	Pakistan	Non-Responsive	Single bidder	As per PPRA Rule goods can be procured from the single bidder	Single bidder can be accepted under PPRA Rules	Responsive subject to verifications of rates from Market
6	RO Plant	AMS-6000GPD	UA/ USA/ China/Taiwan	Non-Responsive	No Technical Data provided	Technical data provided with grievance letter	Data provided, Observation removed	Responsive

[Handwritten signatures and initials are present at the bottom of the page, including a large signature on the left and several initials on the right.]

M/s Sigma Int.

Sr. No	Item Name	Model	Make	Status	Observations	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Suction Machine Light Duty	New Hospivac 400	CAMI, Italy	Sub-Responsive	1-Vacume continuous adjustment 2-Triple Flow safety device	1-Vacume continuous adjustment is available 2-Triple flow is available with another term	Does not have triple flor & Noise level is high	Non- Responsive
2	Suction Machine Heavy Duty	New Hospivac 400	CAMI, Italy	Sub-Responsive	1-Vacume continuous adjustment 2-Triple Flow safety device	1-Vacume continuous adjustment is available 2-Triple flow is available with another term	Does not have triple flor & Noise level is high	Non-Responsive
3	Electrosurgical Unit/ Diathermy	haRTT 300	Kentamed, Bulgaria	Non-Responsive	1-No Sale Reference	Sale Reference is attached as annex-D with this letter	1-Supply order is from CMH Bahawalpur 2-In Provided Supply order Model is not mentioned	Non- Responsive
4	Defibrillator	Reanibex-700	Osatu, Spain	Non-Responsive	1-Synchronized outpur with ECG 2-HR Display 3-Auto test	1-Synchronized output with ECG Machine (Technical leaflet attached) 2-HR display is available 3-Auto test is available	Observations are verified from the technical leaflet. Therefore, observations are settles	Responsive
5	Life Line Trolley	Persolife Inox PCL M	Francehopital, Italy	Non-Responsive	1-No Technical Data/ Leaflet provided	Technical Leaflet attached as Annex-G	No Technical Leaflet as Annex-G attached	Responsive
6	Electrohydraulic OT Table	SU-03	Famed, Poland	Non-Responsive	1-No Sale Reference	Supply order enclosed with this letter	Model is not mentioned on supply order & Gajju Khan Medical college is not a public sector Institution. Back spiring administration adjustment	Responsive
7	Electronic Autoclave 1STU	P-3270 H	CISA, Italy	Non-Responsive	1-No Past performance & Sale Ref	Supply order enclosed with this letter	Sale Ref. is attached (EDO Health Rawalpindi) Model not mentioned	Non- Responsive
8	Medium Steam Sterlizer 4STU	P-4212 H Ev	CISA, Italy	Non-Responsive	1-No Past performance & Sale Ref	Supply order enclosed with this letter	Sale Ref. is attached (EDO Health Rawalpindi) Model not mentioned	Non- Responsive
9	Cleaning & Washing Unit	LA Washing Sink 75 LT	CISA, Italy	Non-Responsive	1-No Past performance & Sale Ref	Supply order enclosed with this letter	Supply order with out model & Gajju Khan Medical college is not a public sector Institution	Responsive
10	Ultrasonic Cleaner	Ultrasons HD 3000868	JP Selecta, Spain	Non-Responsive	1-No Past performance & Sale Ref	Supply order enclosed with this letter	No Supply order attached	Non- Responsive

[Handwritten signatures and initials at the bottom of the page]

Clinical Life Vs Mediland

Sr. No	Item Name	Model	Make	Status	Observations Raised by Clinical Life	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Electronic Autoclave 1STU	HS33	Getinge, Sweden	Responsive	<p>1-Door Material is not of AISI 316L</p> <p>2-Jacket is not made of AISI316L</p> <p>3-No UPS Installed by Manufacturer</p> <p>3-Country of Origin is not sweden rather Poland (should be rejected on hiding the fact)</p> <p>4-Minimum 3 years of experience is not belong to Mediland</p>	<p>1-The Sterilizer Chamber is constructed from solid high quality type 316LTi/W.Nr 1.4571 stainless steel for optimal protection against Corrosion.</p> <p>2-Chamber jacket is a part of chamber and mounted around and on the outside of chamber made of 316L</p> <p>3-UPS will be provided from the same Manufacturer.</p> <p>4-Performance reports from various institution are attached</p>	<p>Observation raised by Clinical Life were valid</p> <p>(Already Discussed in detail in M/s Total Technologies Vs Mediland)</p>	Non-Responsive
2	Medium Steam Sterilizer 4STU	TS330EC1 NX	Getinge, Sweden	Responsive	<p>1-Door Material is not of AISI 316L</p> <p>2-No UPS Installed by Manufacturer</p> <p>3-Country of Origin (Turkey)</p> <p>4-OEM not Getinge Sweden</p> <p>5-CE Certificate is issued on the name of Trans Medikal</p> <p>6-Minimum 3 years of experience is not belong to Mediland</p>	<p>1-The Sterilizer Chamber & doors construct from solid high quality 316LTi/ W.Nr 1.4404 stainless steel</p> <p>2-UPS will be provided from the same Manufacturer.</p> <p>3-As per bidding document (Health & SZMC) 3: Country of origin "3.1: Country of Manufacturer should be from USA, Europe & Japan, unless otherwise any other country of manufacturer is mentioned in the specifications. However, country of origin of equipment could be from any geographical region of the world as per law of Pakistan"</p> <p>Country of manufacturer is Sweden</p> <p>4-OEM is attached form Getinge, Sweden. Trans by Getinge Medikal Aletler Ve Tic A.S is a wholly owned factory of Getinge AB.</p>	<p>Observation raised by Clinical Life were valid</p> <p>(Already Discussed in detail in M/s Total Technologies Vs Mediland)</p>	Non-Responsive

M/s Clinical Life Vs Radiant Medical

Sr. No	Item Name	Model	Make	Status	Observations by Clinical Life	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Ultrasonic Cleaner	DT 1028 H 28	Bandelin for Matachana, Spain	Responsive	Quoted Model don't have digital display	Have digital display please visit the website	Observation is not valid	Responsive

M/s Clinical Life Vs Medequips

Sr. No	Item Name	Model	Make	Status	Observations by Clinical Life	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Patient Shifting Trolley	PK 5114	Paramount, Japan/Indonesia	Responsive	1-Manufacturing in Indonesia 2-TR & ATR is 15/-15 degree while PK 5114 have 12/-6 degree 3-Paramount trolley don't have wire basket	1-Country of origin is Japan while manufacturing is Indonesia 2-TR is 12 degree while ATR is 6degree 3-storage tray is available	1-Country of origin is Japan while manufacturing is Indonesia 2-TR is 12 degree while ATR is 6degree (Observation valid) 3-storage tray is available instead of wire basket	Non-Responsive

M/s Clinical Life Vs KASBN Int.

Sr. No	Item Name	Model	Make	Status	Observations by Clinical Life	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Patient Shifting Trolley	Tarsis	Industrias H. Pardo, Spain	Responsive	1-TR & ATR is 12/-8 degree	Please see technical offer	1-TR & ATR is 12/-8 degree Observation accepted	Non-Responsive

M/s Clinical Life

Sr. No	Item Name	Model	Make	Status	Observations	Reply by the firm	Review by the Technical Member	Decision of the Committee
1	Electronic Autoclave 1STU	Steri 21 AJC 404066-ID GI	A.J. Costa, Portugal	Non-Responsive	1-No Heat Exchanger/Air Detector Optional 2-Air Detector is not available in the quoted Model	1-Said parameter is available in out quoted Model, Technical Leaflet attached for ready Ref. 2-Air detector is available in the quoted model as optional	1-Heat Exchanger is available as standard 2-Air Detector is available as demanded in optional Observation cleared	Responsive
2	Medium Steam Sterlizer 4STU	Amaro 5000-707070 - 2D GI	A.J. Costa, Portugal	Non-Responsive	No Built in water saving system, automatic heat exchanger & air detector	1-Said parameter is available in out quoted Model, Technical Leaflet attached for ready Ref. 2-Air detector is available in the quoted model 3-Automatic heat exchanger is available	1-Built in water saving system is available 2-Heat Exchanger is available as standard 3-Air Detector is available as demanded in standard (Observation cleared)	Responsive
3	Cleaning & Washing Unit	S-S-04	S.S.Corporation, Pak	Non-Responsive	1- Drain Valves not mentioned & Siphon tap are absent	Drain Valve is available and Siphon Tap is available	1-Drain valves are available 2-Siphon tap is available Observations removed	Responsive
4	Ultrasonic Cleaner	QC6-02 Quick Clean	Newmed, Italy	Non-Responsive	1- No Sale Ref. & Past performance	Sale Ref. & Past performance Certificates are enclosed	Ref. & performance are enclosed with their reply	Non- Responsive
5	Operating Laparoscope	CMOS 1/2" Chip	Ackermann, Germany	Non-Responsive	1-Imaging system don't have backward & forward compatibility for upgradation	1-Imaging System backward & forward compatibility available for upgradation (Data sheet attached) 2-Both options Picture-in-	1-Backward & Forward compatibility is available 2-Picture in Picture mode is available in Camera & Monitor	Responsive

[Handwritten signature]

[Handwritten signature]


[Handwritten signature]

[Handwritten signature]


[Handwritten signature]


[Handwritten signature]

					<p>2-Picture in Picture mode control via camera head button is not mentioned.</p> <p>3-Peripheral control is not available</p> <p>4-Video capturing in full HD quality (MPEG4) format via camera Head button is not available.</p> <p>5- 05 Individual Preset or better is not mentioned</p> <p>6- Three patient data backup or better is not mentioned</p> <p>7-No Sale Ref. & Past performance</p>	<p>picture & Picture out mode available. User can control via camera head buttons or via HD Monitor</p> <p>3-Two peripheral outputs & control with camera head button available.</p> <p>4-Integrated HD Quality video recording of MPEG4 format available with camera head buttons</p> <p>5-06 individual preset available.</p> <p>6-Unlimited user profile & Up-to nine patient data-backup available.</p> <p>7-Sale Reference & Past performance Certificate attached.</p>	<p>3-Peripheral control is available</p> <p>4-Integrated HD Camera recording is possible in MPEG4 format</p> <p>5-Six preset available</p> <p>6-Unlimited User profile data is possible for 9 patients</p> <p>7-Performance certificate is enclosed for Ackerman in Fatima Memorial Hospital, Lahore (from private sector, therefore not acceptable)</p>	
10	Medical Gasses	Multi	Precision UK, HGM Poland, Atlas Copco, UK, Portugal	Non-Responsive	<p>1-Compressor capacity is 918 Ltr instead of 1000/ L/ Min at 10 bar</p> <p>2-Air Dryer system is under capacity of 900 Ltr.</p>	<p>1-our quoted Model LF10 fulfil the Capacity of 1000 L/Min as per requirements.</p> <p>2-the dryer MED15 not only fulfil the compressor requirements rather it is over the capacity. We quoted this model as per manufacturer advise as it's from same manufacturer.</p>	<p>1-Compressor capacity of LF 10 is 15.67L/Sec (940 Liters/ Min), However at a frequency of 60 Hz its outflow attains 1452 Ltrs/Min</p> <p>2-Dryer capacity of MED 15 is 18.0L/Sec</p>	Non-Responsive



Engr Awais Bin Tariq
 Bio-Medical Engineer
 SZMC/SZH, RYK


Muhammad Akbar Athar
 Assistant Manager Contracts
 E&D Wing, SZMC/SZH, RYK


Dr. Ali Raza Zaidi
 Director Emergency
 SZMC/ SZH, RYK


Dr. Nuzhat Rasheed
 Associate Prof. of Gynecology
 SZMC/ SZH, RYK


Dr. Ghulam Rabbani
 Medical Superintendent
 SZH, RYK


Prof. Dr. Masood ul Haq
 Prof. of Pulmonology
 SZMC/SZH, RYK